

Installation of Leica SKI software **under WindowsNT**

The following statements hold true for **SKI version 2.10 and 2.11 and 2.2 and 2.3 or higher!!!**

Do **not** install SKI 2.0 or lower under Windows NT!!

Run the installation program from the SKI disks now and install SKI on your PC. Insert disk no. 1 and start the installation program of SKI by executing the file SETUP . EXE. Follow the instructions and complete the installation.

If you want to install SKI 2.xx software under Windows NT 3.51 or 4.0 you need special drivers for the dongle. These drivers are available on a disk free of charge from your local Leica representative.

When you have got this disk, proceed as follows:

Copy the self-extracting file NTDRIVER.EXE from the disk to your hard disk and execute it!

The directory C:\NTDRIVER\ is created.

The drivers for WindowsNT 3.51 are stored under C:\NTDRIVER\NT351\ .

The directory C:\NTDRIVER\NT40\ contains the files for WindowsNT 4.0.

For Windows NT 4.0 Microsoft has released a bug update, it is called Service Pack 2.0 and 3.0. Customers who use NT 4.0 should look for this update, because several bugs of NT 4.0 are handled. One of the corrected files is needed for a proper SKI installation under NT 4.0!


If you have **not** installed this update, you can find the required file together with the dongle drivers on the disk. The file C:\WINNT40\SYSTEM32\NTVDM.EXE has to be replaced by the new NTVDM.EXE. The new NTVDM.EXE file can be found under C:\NTDRIVER\ NT40\SYSTEM . Now the dongle-driver will show its full functionality.

Don't replace the NTVDM.EXE file if you have installed NT Service Pack 2 or 3!

Please note that this replacement is only necessary if you didn't install the Service Pack 2.0 provided by Microsoft! Compare the date of the NTVDM.EXE from Microsoft with that from Leica. You should only replace the file delivered by Microsoft if the file from Leica is more recent!! Future versions of WindowsNT may contain the corrected NTVDM.EXE! Before you copy the new NTVDM.EXE file to the C:\WINNT40\SYSTEM32\ directory, rename the old file!! **Do not overwrite the original file!**


For installing the drivers for NT 3.51 or NT 4.0 just run INSTALL.BAT from the C:\NTDRIVER\NT351\ or C:\NTDRIVER\NT40\ directory!

The program prompts then and asks for the directory of the driver. Now you have to enter the path, e.g. C:\NTDRIVER\NT40\i386 .



After installing SKI under Windows NT you have to set the environment variables (make sure the correct path is set!). This has to be done in Windows NT, in the Control Panel, in the submenu System and then Environment.


The Control Panel can be accessed under Start / Settings:



Enter the following lines manually!

Don't forget the backslash at the end of the path!!!!

Variable	Value
DBGLOBAL	C:\ski\db\dbglocal\
DBPROJ	C:\ski\db\dbproj\
DBTRANS	C:\ski\db\dbtrans\



Now the installation of SKI under Windows NT is complete!

Afterwards you have to reboot your computer!!

For further informations contact your local Leica dealer!