


FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
CERTIFIED CORNER RECORD

CORNER DESCRIPTION:

S 1/4 corner of Section 25,  
 Twp 20 S, Rge 27 E,  
 Tallahassee Base Meridian,  
ORANGE County(s), Florida.

MONUMENTATION DESCRIPTION:

Describe original monument and accessories, or subsequent restoration. Give sources of information. (if no attempt was made to search for the original monument and accessories, this information is not necessary.)

SEE CERTIFIED CORNER RECORD NUMBER 30048, 28001, 13599

## Description of corner evidence found:

RECOVERED 4X4 CONCRETE MONUMENT 18"+ BELOW ROAD GRADE.  
 (TOP BROKEN)

State method(s) to determine corner location (lost corners only):

N/A

HORIZONTAL POSITION INFORMATION (if determined):

Latitude 28°42'45.66539" N Longitude 81°34'04.35246" W  
 Y(Northing) 592253.687 X(Easting) 474137.055 Zone EAST  
 Convergence -0°0'22.368" Scale factor 0.999979152  
 Coordinate determination (circle one): Field traverse GPS  
 Horizontal datum (circle one): NAD27 NAD83(1986) NAD83(1990) other (explain)

Order of accuracy as defined in Standards and Specifications for Geodetic Control Networks published by the Federal Geodetic Control Committee (circle one):  
 1st, 2nd, 3rd, class \_\_\_\_\_

or Minimum Technical Standards (Chapter 21HH-6, F.A.C.) ratio of closure for field data (example 1:10,000), \_\_\_\_\_. This does not specify an order of accuracy.

Control point(s) used for survey:

ORANGE COUNTY GEODETIC NETWORK


APR 1 8 1999

Comments: The purpose of this Survey was to establish state plane coordinate values on existing certified corners. No attempt was made to prove the validity of the location of the existing certified corners.

SKETCH:

DOC. #

0048451



All bearings and distances must be from the corner to the witness. Indicate whether corner was found, set, or replaced and show north arrow.

REFERENCE MEASUREMENTS (at least three vicinity references must be given below even if they appear on the above sketch):

Description	MAG. Bearing	FEET Distance
RECOVERED POURED CONCRETE MONUMENT P.R.M.	N 03° E	11.48'
REC. SCREW & DISK IN S. FACE OF P.P. #7-899 ON N. SIDE OF YOTHERS ROAD	N 42° E	50.28'
REC. NAIL & DISK IN TOP OF N.W. FENCE CORNER POST	S 49° E	44.22'
REC. P.K. NAIL & WASHER IN W. FACE OF P.P. #740067 E. SIDE OF HERMIT SMITH ROAD	S 11° E	54.39'
REC. NAIL & DISK #4081 IN N. FACE OF P.P. #775391 N. SIDE OF YOTHERS ROAD	N 75° W	175.58'

SURVEYORS CERTIFICATE: I certify the monument and accessories indicated above were field located on AUGUST 30, 1981.

Daniel M. Hico 4165  
 SURVEYOR - P.R.M.  
4/13/84  
 Orange County Survey Section  
 4200 South John Young Parkway  
 Orlando, Florida 32839-9205

1121  
 P. 20X4



SEND TO:  
 Department of Environmental Protection  
 Bureau of Survey and Mapping  
 3800 Commonwealth Boulevard  
 Tallahassee, Florida 32399  
 (904) 65-6011(14)  
 REV. 10/18/83  
 PAGE 2 OF 2

Completion checked by: B. Hinton  
 Accepted and filed: 5-1-84  
 B.L.M. - I.D. 36660025 S.N.R. USE ONLY