


0047897

SKETCH:

DOC. #



CROSS SECTION 10-66
PAGE 65

All bearings and distances must be from the corner to the witness. Indicate whether corner was found, set, or replaced and show north arrow.

REFERENCE MEASUREMENTS (at least three vicinity references must be given below even if they appear on the above sketch):

Description	MAG. Bearing	FEET Distance
REC. J.W. & G NAIL & DISK IN S. FACE OF 32° OAK TREE	N 72° E	75.52'
REC. J.W. & G NAIL & DISK IN N.E. FACE OF 27° OAK TREE	S 66° E	75.85'
REC. J.W. & G NAIL & DISK IN S.W. FACE OF P.P. #780693	S 36° E	37.22'
REC. J.W. & G NAIL & DISK IN S. FACE OF 37° OAK TREE	S 70° W	41.61'
REC. J.W. & G NAIL & DISK IN S.W. FACE OF 19° OAK TREE	N 55° W	88.40'

SURVEYORS CERTIFICATE: I certify the monument and accessories indicated above were field located on DECEMBER 3, 1991.

Alan Z. McKee 4188

SIGNATURE - PLS. NO.
1-28-94

DATE

Orange County Survey Section

FIRM OR AGENCY

4200 Whitcomb Avenue

ADDRESS

Orlando, Florida 32839-9205

CITY

STATE

Completeness checked by: [Signature]

Accepted and filed: 3-1-94

DATE

B.L.M. - I.D. 01C6003

D.M.R. USE ONLY

11/21

SEND TO:

Department of Natural Resources
Bureau of Survey and Mapping
3900 Commonwealth Boulevard
Mail Station 105
Tallahassee, Florida 32399


DNR 53-061(18)
REV. 2/7/91
PAGE 2 OF 2



FLORIDA DEPARTMENT OF NATURAL RESOURCES
CERTIFIED CORNER RECORD

CORNER DESCRIPTION:

S 1/4 corner of Section 36
Twp 20 S, Rge 27 E
Tallahassee Base Meridian,
ORANGE County(s), Florida.

MONUMENTATION DESCRIPTION:

Describe original monument and accessories, or subsequent restoration. Give sources of information. (If no attempt was made to search for the original monument and accessories, this information is not necessary.)

SEE CERTIFIED CORNER RECORD NUMBER 32381, 30716, 2162

RECEIVED

Description of corner evidence found:

RECOVERED 4X4 CONCRETE MONUMENT #1680 IN WELL BOX

FEB 2 1994

State method(s) to determine corner location (lost corner) SURVEY & MAPPING
N/A

HORIZONTAL POSITION INFORMATION (if determined):

Latitude 28°47'53.49096" N Longitude 81°34'01.05938" W
Y(Northing) 1688981577 X(Easting) 474405.227 Zone EAST
Convergence -0°16'20.133" Scale factor 0.999979040

Coordinate determination (circle one):

Field traverse

GPS

Horizontal datum (circle one): NAD27 NAD83(1986) NAD83(1990) other (explain)

Order of accuracy as defined in "Standards and Specifications for Geodetic Control Networks" published by the Federal Geodetic Control Committee (circle one):
1st, 2nd, 3rd, class _____

or Minimum Technical Standards (Chapter 21HH-6, F.A.C.) ratio of closure for field data (example 1:10,000), _____. This does not specify an order of accuracy.

Control point(s) used for survey:

ORANGE COUNTY GEODETIC NETWORK

Comments:

The purpose of this Survey was to establish state plane coordinate values on existing certified corners. No attempt was made to prove the validity of the location of the existing certified corners.