

KEY TO SURVEY MARKS

In the following list "Standard Rod and Cap" denotes a Punchmark on a 2 in. Aluminum Cap stamped "KENT MCMILLAN, SURVEYOR, RPLS 4341", numbered and with the additional stampings noted, affixed to a 5/8 in. Iron Rod.

"Standard Spike and Washer" denotes a Punchmark on a 3/8 in. Steel Spike with a 2 in. Aluminum Washer stamped "KENT MCMILLAN, SURVEYOR, RPLS 4341" and numbered as noted.

No. Description

- 29** Punchmark on Head of 3/8 in. Steel Spike set
- 105** Found 3/8 in. Iron Rod (0.4 ft. Southwest of 2 in. Pipe Fence Corner Post, in what appears to be an old Post Hole. From this Rod:
- Spike and Washer No. 106 on the line of the remnants of an old Wire Fence running Southerly bears S 2-09-40E, 63.04 ft.
 - Iron Rod No. 148 bears N 8-47-55W, 32.52 ft.,
 - Concrete R-O-W Marker No. 141 bears N 8-47-55W, 32.52 ft. and N68-54-03E, 34.36 ft.,
 - Rod and Cap No. 327 bears N 2-06-41W, 33.63 ft. and
 - Concrete R-O-W Marker No. 141 bears N 2-06-41W, 33.63 ft. and N68-56-48E, 30.34 ft.
- I take Iron Rod No. 105 to be the same "iron pin" described as marking "the recognized northwest corner of the W.S. Allen Survey Number 947" in the Deed to Patrick G. Greene recorded as Doc. No. 200406006173 CCOPR and also in the position of the "post at the Northwest corner of said W.S. Allen Survey and re-entrant corner of said [Z.] Williamson Survey" described in the Correction Deed to W.N. George recorded in Vol. 189 at Pg. 231 CCCR.
- 106** Set Standard Spike and Washer on the South side of the Stub of an old, broken 2 in. Cedar Post on the line of a former Wire Fence.
- 122** Set Standard Rod and Cap "122, FD OLD RM" at Center of 3.6 ft. diameter Rock Mound found (more than 25 Large Rocks, 8 of which are about 2 - 4 ft. North of the Rod and Cap and taken to be the fallen upper part of the original Rock Mound. This is the original NW corner of the Wm. C. Chumney Survey. Noting that from Rod and Cap No. 122:
- the Center of the stump of a 10 in. Live Oak No. 131, very decayed, but recognizable as a Live Oak, bears N88-56-44W 85.37 ft. ,
 - Center of Top of Lone Man Mountain No. 96 bears N21-15-21E, approximately 55,615 ft.,
 - Center of Top of West Twin Sister Mountain No. 95 bears N17-14-24E, approximately 29,744 ft., and
 - Center of Top of Lone Woman Mountain No. 97 bears N15-36-50E, approximately 53,230 ft.,
- the Cedar forest that has grown up around this corner presently obstructing the view of the mountains from this corner at ground level.
- 123** Found 3/8 in. Iron Rod (6" Up), 1.25 ft. North of 2 in. Pipe Corner Post of Newer Wire Fence from which Rod and Cap No. 200 at the original Northeast corner of the W.S. Allen Survey bears S59-32-25W, 14.20 ft.

- 128 Center of 12 in. Cedar Elm with old Blaze Scar on NE face, at Angle Point of Wire Fence, old 5-strand Barb Wire Fence running to Cedar Post No. 158 ingrown into East Face of Elm. The original SW corner of the 1.5 ac. tract conveyed to Jeff D. Biles as described in WD recorded Vol. 72 Pg. 589 CCDR and an Angle Point on the East line of the 5 ac. tract conveyed to W.N. George by Correction Deed recorded in Vol. 189 at Pg. 231 CCDR.
- 131 Center of 10 in. Live Oak Stump, very decayed, but recognizable. Outer layers of trunk, now broken and fallen to ground, show scar on side once facing Rock Mound No. 122, remains of original bearing tree of NW corner of W.C. Chumney Survey.
- 132 Set Spike and Washer "132" in center of Live Oak Stump found (once larger than 10 in., now dead), original bearing tree of NE corner of W.S. Allen Survey No. 947.
- 133 Set Standard Rod and Cap "133, FD ROW CM" in Center of Stub of broken Concrete R-O-W Marker
- 134 Set Standard Rod and Cap "134, FD ROW CM" in Center of Stub of broken Concrete R-O-W Marker
- 135 Set Standard Rod and Cap "135, FD ROW CM" in Center of Stub of broken Concrete R-O-W Marker
- 136 Punchmark on 3/8 in. Spike set in Drill Hole at Center of Stub of broken Concrete R-O-W Marker
- 137 Punchmark on 3/8 in. Spike set in Drill Hole at Center of Stub of broken Concrete R-O-W Marker
- 138 Scribed "X" on Top Center of Concrete R-O-W Marker found (intact and plumb)
- 139 Punchmark on 3/8 in. Spike set in Drill Hole at Center of Stub of broken Concrete R-O-W Marker
- 140 Scribed "X" on Top Center of Concrete R-O-W Marker found (intact, but leans approx. 0.4 ft. toward Concrete Monument No. 139)
- 141 Scribed "X" on Top Center of Concrete R-O-W Marker found (intact and plumb)
- 142 Scribed "X" on Top Center of Concrete R-O-W Marker found (intact and plumb)
- 143 Scribed "X" on Top Center of Concrete R-O-W Marker found (intact, but leans approx. 0.50 ft. away from Concrete Monument No. 142)
- 144 Scribed "X" on Top Center of Concrete R-O-W Marker found (intact and plumb)
- 145 Scribed "X" on Top Center of Concrete R-O-W Marker found (intact and plumb)
- 146 Found 3/8 in. Iron Rod with old, faded orange Plastic Flagging
- 147 Center of Base of old 2"x 24" Cedar Stake found in Rock Mound (more than 16 Large & Medium size Rocks), taken for NW corner of 5.6 ac. Tract 2 placed by T.A. Breeze, LSLs in May, 1949 described in Affidavit recorded Vol. 91 Pg. 359 CCDR
- 148 Found 1/2 in. Iron Rod taken for same stake placed by Ken L. Reininger, RPLS in 1991 to mark the NE corner of a 1.05 ac. tract as described in Quitclaim Deed recorded Vol. 910 Pg. 158 CCDR, noting that from Rod 148, Concrete R-O-W Marker No. 141 bears N68-54-00E, 34.35 ft.

- 149 Found 1/2 in. Iron Rod (7 in. Up) on line of newer Wire Fence, on East side of Stump of 8 in. Cedar with fragments of old Wire Fence in South face. I take this Rod to be the same described in the Deed to Patrick B. Greene recorded as Doc. No. 200406006173 CCOPR as marking an Angle Point on the recognized North line of the W.S. Allen Survey. Rod No. 149 is 4.40 ft. North of the original North line of the W.S. Allen Survey. From Rod No. 149, Rod and Cap No. 230 bears S5-36-19W, 4.44 ft.
- 152 Found 1/2 in. Iron Rod (7 in. Up) 0.25 ft. South of newer Wire Fence. I take this Rod to be the same described in the Deed to Patrick B. Greene recorded as Doc. No. 200406006173 CCOPR as marking an Angle Point on the recognized North line of the W.S. Allen Survey. Rod No. 152 is 1.19 ft. North of the original North line of the W.S. Allen Survey.
- 158 Center of Base of old 4 in. Cedar Post with old 5-strand Barb Wire Fence running from Cedar Elm No. 128, at Fence Corner, the same Cedar Post described as marking the 1.5 ac. tract conveyed to Jeff D. Biles in WD Vol. 72 Pg. 589 CCDR, but found by resurvey not to actually be on the South line of the Right-of-Way of R.M. Hwy. 32, from Post 158:
- Live Oak 162 bears N82-27-24E 350.00 ft. (record call: N83-30E, 350 ft. per deed to Biles)
- 159 Found 3/8 in. Iron Rod with old, faded orange Plastic Flagging
- 160 Found 3/8 in. Iron Rod at base of Live Oak No. 162
- 162 Center of 31 in. diameter Live Oak. The same tree described in 1940 as a 24 in. diameter Live Oak marking the NE corner fo the 1.5 ac. tract conveyed to Jeff D. Biles in WD Vol. 72 Pg. 589 CCDR, but found by resurvey not to actually be on the South line of the Right-of-Way of R.M. Hwy. 32
- 164 Found 1/2 in. Iron Rod 0.85 ft. North of newer Wire Fence. I take this Rod to be the same described in the Deed to Patrick B. Greene recorded as Doc. No. 200406006173 CCOPR as marking an Angle Point on the recognized North line of the W.S. Allen Survey. Rod No. 164 is 3.17 ft. North of the original North line of the W.S. Allen Survey
- 166 Punchmark on Head of 3/8 in. Steel Spike set
- 167 Point at Center of Base of 7 in. Cedar with remnants of old Wire Fence stapled to it from which:
- Spike No. 166 set for reference bears S11-16-26E, 6.22 ft.
- 170 Punchmark on Head of 3/8 in. Steel Spike set
- 172 Point at Stump of 5 in. Cedar with remnants of old Wire Fence stapled to it from which:
- Spike No. 170 set for reference bears S5-32-43E, 5.41 ft.
- 175 Punchmark on Head of 3/8 in. Steel Spike set
- 176 Point at Center of Base of 8 in. Cedar with remnants of old Wire Fence stapled to North face from which:
- Spike No. 175 set for reference bears S28-23-23E, 5.76 ft.
- 177 Punchmark on Head of 3/8 in. Steel Spike set
- 178 Point at approximate Center of Base of 2 in. Pipe Post of newer Wire Fence from which:
- Spike No. 177 set for reference bears S17-51-11E, 5.70 ft.
- 181 Set Standard Rod and Cap "181, OLD POST" by Stub of old Cedar Post found approx. 0.45 ft. East of 3 in. Pipe Post on North side of Gate

- 185 Point at approximate Center of Base of 12 in. Cedar at Angle Point of older Wire Fence and newer Wire Fence from which:
- Spike and Washer No. 29 bears S5-08-27E, 7.65 ft.
- 186 Punchmark on Head of 3/8 in. Steel Spike set
- 187 Point at approximate Center of Base of 10 in. Cedar with old Wire stapled to South face from which:
- Spike No. 186 set for reference bears S7-54-17W, 6.12 ft.
- 188 Punchmark on Head of 3/8 in. Steel Spike set
- 190 Point at approximate Center of Base of 6 in. Cedar with old Fence Wire stapled to South face from which:
- Spike No. 188 set for reference bears S5-41-45W, 6.14 ft.
- 191 Center of Base of old 5 in. Cedar Post with old Fence Wire attached to it.
- 200 Set Rod and Cap "200, NE ALLEN" (approximately 5.4 ft. South of Newer E-W Wire Fence) to mark the original NE Corner of the W.S. Allen Survey No. 947, noting that from Rod and Cap NO. 200:
- Rod and Cap No. 122 at the NW corner of the W.C. Chumney Survey bears N 1-55-05W, 553.39 ft. = 199.220 vrs (record call: NORTH, 200 vrs.),
- Spike and Washer No. 132 in old Live Oak Stump bears N 1-55-05W 11.11 ft.= 4.000 vrs. (record call: NORTH, 4 vrs.), and
- Rod 123 bears N59-32-25E, 14.20 ft.
- 209 Punchmark on Head of 3/8 in. Steel Spike set
- 210 Point at approximate Center of Base of 9 in. Cedar with old Fence Wire stapled to North face from which:
- Spike no. 209 set for reference bears S8-25-10W, 5.49 ft.
- 213 Punchmark on Head of 3/8 in. Steel Spike set
- 214 Point at Center of Base of 2 in. Pipe Post of newer Wire Fence from which:
- Spike No. 213 set for reference bears S17-15-25W 6.06 ft.
- 215 Punchmark on Head of 3/8 in. Steel Spike set
- 216 Point at approximate Center of Base of 6 in. Cedar with old Fence Wire stapled to South face from which:
- Spike No. 215 set for reference bears S18-20-38W, 6.16 ft.
- 217 Punchmark on Head of 3/8 in. Steel Spike set
- 218 Point at approximate Center of Base of old 2-1/2 in. Cedar Fence Post from which:
- Spike No. 217 set for reference bears S8-39-51W, 6.06 ft.
- 230 Set Standard Rod and Cap "230, N LINE ALLEN" on North line of W.S. Allen Survey. Rod No. 149 bears N5-36-19E, 4.44 ft.
- 300 Unmarked Point on Engineer's Centerline for R.M. Hwy. 32
- 301 Unmarked Point at intersection of tangents of Engineer's Centerline for R.M. Hwy 32
- 302 Unmarked Point on Centerline of R-O-W of R.M. Hwy. 32 at Engineer's Station 666+73.5
- 303 Unmarked Point on Centerline of R-O-W of R.M. Hwy. 32 at Engineer's Station 660+79.1
- 304 Unmarked Point at intersection of tangents of Engineer's Centerline for R.M. Hwy 32
- 305 Unmarked Point on Centerline of R-O-W of R.M. Hwy. 32 at Engineer's Station 651+76.9
- 306 Unmarked Point on Centerline of R-O-W of R.M. Hwy. 32 at Engineer's Station 649+81.7
- 307 Unmarked Point at intersection of tangents of Engineer's Centerline for R.M. Hwy 32

- 308 Unmarked Point on Centerline of R-O-W of R.M. Hwy. 32 at Engineer's Station 643+96.7
- 309 Unmarked Point on Centerline of R-O-W of R.M. Hwy. 32 at Engineer's Station 642+07.7
- 310 Unmarked Point at intersection of tangents of Engineer's Centerline for R.M. Hwy 32
- 311 Unmarked Point on Centerline of R-O-W of R.M. Hwy. 32 at Engineer's Station 638+74.4
- 312 Unmarked Point on Sout line of R-O-W of R.M. Hway. 32
- 313 Point on Top of Concrete R-O-W Marker No. 138 from which:
- "X" No. 138 on said Marker bears S13-50-44E, 0.02 ft.
- Spike No. 137 bears N13-50-44W, 100.02 ft.
- 314 Unmarked Point at Center of 2814.79 ft. radius curve
- 315 Set Standard Rod and Cap "315" on South line of 100 ft. wide R-O-W of R.M. Hwy. 32 at intersection of prolongation of West line of 1.5 ac. tract conveyed to Jeff D. Biles as described in WD Vol. 72 Pg. 589 CCDR, noting that from Rod and Cap NO. 315:
- Iron Rod No. 159 bears S61-40-24E, 1.38 ft.
- Cedar Post No. 158 bears S19-16-05E, 4.75 ft.
- 316 Set Standard Rod and Cap "316" in Asphalt Pavement of a Driveway, approx. 2.5 ft. North of South Edge of Pavement
- 317 Unmarked Point at Center of 1959.86 ft. radius curve
- 318 Point approximately marked by broken Concrete R-O-W Marker found, noting that from Point No. 318:
- Standard Rod and Cap No. 134 in said marker bears N13-25-10E, 0.40 ft. and
- "X" No. 145 on Concrete R-O-W Marker found bears N13-18-55E, 100.00 ft.
- 319 Point approximately marked by broken Concrete R-O-W Marker found, noting that from Point No. 319:
- Spike No. 139 in said Marker bears N21-53-25W, 0.24 ft.
- "X" No. 140 on Marker leaning approx. 0.52 ft. toward Spike No. 139 bears N21-53-25W, 99.48 ft.
- 320 Point approximately marked by Concrete R-O-W Marker No. 143, noting that from Point No. 320:
- Concrete R-O-W Marker No. 142 bears N1-43-52W, 100.00 ft.
- "X" No. 143 on said Marker (leaning approx 0.44 ft. away from Marker No. 142) bears S1-43-52E, 0.44 ft.
- 321 Unmarked Point at Center of 1004.93 ft. radius curve
- 322 Set Standard Rod and Cap "322" in what appears to be an old Post Hole on the South side of the Asphalt Driveway
- 324 Point on Line of former Wire Fence from which Concrete R-O-W Marker No. 139 bears N 2-05-00W 80.19 ft.
- 327 Set Standard Rod and Cap "327" on South line of Highway R-O-W to mark NW corner of tract conveyed to W.N. George by Correction Deed recorded in Vol. 189 at Pg. 231 CCDR, noting that from Rod and Cap No. 327:
- Cedar Stake No. 147 bears S2-06-41E, 1.08 ft.
- Iron Rod No. 105 bears S2-06-41E, 33.63 ft.
- Iron Rod No. 146 bears N60-48-10W, 0.50 ft.
- Iron Rod No. 148 bears S68-33-08W, 4.01 ft.
- Concrete R-O-W Marker No. 141 bears N68-56-48E, 30.34 ft.